


外径基准型（最大压缩量 45%~75%）



订购编号示例

① 代号 - ② D - ③ L
SCHDA - 5 - 10

■ 劲度系数

⚠ D12 仅限 SCHDAB、SCHDAC、SCHDAD、SCHDD 型。D14 仅限 SCHDD 型。

D	SCHDA	SCHDAB	SCHDAC	SCHDAD	SCHDBA	SCHDBB	SCHDCA	SCHDCB	SCHDD
2	-	0.05 (0.005)	0.2 (0.02)	0.3 (0.03)	0.5 (0.05)	-	-	-	-
3									
4	0.05N/mm (0.005kgf/mm)	0.098N/mm (0.01kgf/mm)				1.5 (0.15)			
5									
6									
8									
10									
12									
13									
14									
16									
20									
S	S = L×71%	S = L×75%	S = L×60%	S = L×45%	S = L×40%	S = L×40%	S = L×35%	S = L×30%	S = L×25%

⚠ 蓝色型号和参数均为外径基准型（最大压缩量 45%~75%）型号

■ SCHDA: S(工作行程) = L×F_a%

① 代号	② D	③ L	d	压紧长度	S	载荷		F _a %
						(N)	(kgf)	
SCHDA	3	5	0.15	1.1	4	0.18	0.018	
		10	0.18	2.5	7	0.35	0.036	
		15	0.18	2.5	11	0.53	0.054	
		20	0.2	3.3	14	0.7	0.071	
		25	0.23	6.2	18	0.88	0.089	
		30	0.23	6.2	21	1.05	0.107	
	4	5	0.18	1.2	4	0.18	0.018	
		10	0.2	1.7	7	0.35	0.036	
		15	0.23	3	11	0.53	0.054	
		20	0.23	3	14	0.7	0.071	
		25	0.26	4.9	18	0.88	0.089	
	6	30	0.26	4.9	21	1.05	0.107	
		5	0.2	1.2	4	0.18	0.018	
		10	0.23	1.8	7	0.35	0.036	
		15	0.26	2.9	11	0.53	0.054	
		20	0.29	4.5	14	0.7	0.071	
		25	0.29	4.5	18	0.88	0.089	
		30	0.29	4.5	21	1.05	0.107	
		10	0.26	2	7	0.35	0.036	
		15	0.3	3.3	11	0.53	0.054	
		20	0.3	3.3	14	0.7	0.071	
		25	0.35	6.5	18	0.88	0.089	
		30	0.35	6.5	21	1.05	0.107	
		35	0.35	6.5	25	1.23	0.125	
		40	0.35	6.5	28	1.4	0.143	
		10	0.3	1.9	7	0.35	0.036	
		15	0.35	3.2	11	0.53	0.054	
		20	0.35	3.2	14	0.7	0.071	
		25	0.4	5.6	18	0.88	0.089	
		30	0.4	5.6	21	1.05	0.107	
		35	0.4	5.6	25	1.23	0.125	
		40	0.45	9.3	28	1.4	0.143	
		45	0.45	9.3	32	1.58	0.161	
		50	0.45	9.3	35	1.75	0.179	

代号	类型	材质	弹簧常数
SCHDA SCHDAB SCHDAC SCHDAD	外径基准型	SUS304-SWPB	± 10%

外径基准型（最大压缩量 45%~75%）

■ SCHDAB: S(工作行程) = L×Fa%

1 代号	2 D	3 L	d	压紧长度	S	载荷		Fa%
						(N)	(kgf)	
SCHDAB	2	5	0.13	1.5	3	0.15	0.015	60
		10	0.13	1.5	6	0.29	0.03	
		15	0.15	2.7	9	0.44	0.045	
		20	0.15	2.7	12	0.59	0.06	
		25	0.18	6.3	15	0.74	0.075	
	3	30	0.18	6.3	18	0.88	0.09	
		5	0.16	0.92	3.75	0.37	0.0375	
		10	0.2	2	7.5	0.74	0.075	
		15	0.23	3.45	11.25	1.1	0.1125	
		20	0.23	3.45	15	1.47	0.15	
	4	25	0.26	6.24	15	1.47	0.15	60
		30	0.26	6.24	18	1.77	0.18	
		5	0.2	1.05	3.75	0.37	0.0375	
		10	0.23	1.84	7.5	0.74	0.075	
		15	0.26	2.86	11.25	1.1	0.1125	
	5	20	0.29	4.64	15	1.47	0.15	75
		25	0.3	5.4	18.75	1.84	0.1875	
		30	0.3	5.4	22.5	2.26	0.23	
		35	0.35	6	26.25	2.55	0.26	
		40	0.35	6	30	2.94	0.3	
	6	5	0.26	1.24	3.5	0.34	0.035	70
		10	0.3	2.1	7.5	0.74	0.075	
		15	0.32	2.64	11.25	1.1	0.1125	
		20	0.35	3.85	15	1.47	0.15	
		25	0.38	5.32	18.75	1.84	0.1875	
	8	30	0.4	6.8	22.5	2.21	0.225	75
		35	0.4	6.8	26.25	2.55	0.26	
		40	0.4	6.8	30	2.94	0.3	
		10	0.35	2.19	7.5	0.74	0.075	
		15	0.4	3.4	11.25	1.1	0.1125	
	10	20	0.4	3.4	15	1.47	0.15	75
		25	0.45	5.4	18.75	1.84	0.1875	
		30	0.45	5.4	22.5	2.21	0.225	
		35	0.5	8.3	26.25	2.55	0.26	
		40	0.5	8.3	30	2.94	0.3	
	12	45	0.5	8.3	33.75	3.33	0.34	75
		50	0.55	12.7	35	3.43	0.35	
		10	0.5	3.25	6	1.18	0.12	
		15	0.5	3.25	11.25	2.21	0.225	
		20	0.55	4.4	15	2.94	0.3	
	13	25	0.55	4.4	18.75	3.68	0.375	75
		30	0.6	6.15	22.5	4.41	0.45	
		35	0.6	6.3	26.25	5.1	0.52	
		40	0.6	6.3	30	5.88	0.6	
		45	0.65	8.45	33.75	6.62	0.675	
	15	50	0.65	8.45	37.5	7.35	0.75	70
		15	0.55	3.3	11.25	2.206	0.225	
		20	0.55	3.3	15	2.942	0.3	
		25	0.6	4.2	18.75	3.68	0.375	
		30	0.65	5.53	22.5	4.41	0.45	
	16	35	0.65	5.53	26.25	5.15	0.525	75
		40	0.7	7.35	30	5.88	0.6	
		45	0.7	7.35	33.75	6.62	0.675	
		50	0.7	7.35	37.5	7.35	0.75	
		60	0.8	13.6	45	8.83	0.9	
	17	70	0.8	13.6	52.5	10.3	1.05	75
		80	0.8	13.6	60	11.77	1.2	
		15	0.6	3.75	10.5	2.06	0.21	
		20	0.6	3.75	15	2.94	0.3	
		25	0.65	4.9	18.75	3.68	0.375	
	18	30	0.65	4.9	22.5	4.41	0.45	75
		35	0.7	6.3	26.25	5.15	0.525	
		40	0.75	8.25	30	5.88	0.6	
		45	0.75	8.25	33.75	6.62	0.675	
		50	0.8	11.2	37.5	7.35	0.75	
	19	60	0.8	11.2	45	8.83	0.9	75
		70	0.85	14.45	52.5	10.3	1.05	
		80	0.85	14.45	60	11.77	1.2	

▲所有 SCHDAA、SCHDAB 型的两端均未进行磨削加工

▲压紧长度为参考值，因此次不同会有少许差异

▲使用次数：100 万次

■ SCHDAC: S(工作行程) = L×Fa%

1 代号	2 D	3 L	d	压紧长度	S	载荷		Fa%
						(N)	(kgf)	
SCHDAC	2	5	0.18	2	2.5	0.49	0.05	50
		10	0.18	2	5	0.98	0.1	
		15	0.23	6	7.5	1.5	0.15	
		20	0.23	6	10	2	0.2	
		25	0.26	11.2	12.5	2.5	0.25	
	3	30	0.26	11.2	15	2.9	0.3	
		5	0.23	1.6	3	0.9	0.09	
		10	0.25	2.1	6	1.8	0.18	
		15	0.3	4.5	9	2.6	0.27	
		20	0.3	4.5	12	3.5	0.36	
	4	25	0.32	6.4	15	4.4	0.45	60
		30	0.32	6.4	18	5.3	0.54	
		35	0.35	9.8	21	6.2	0.63	
		40	0.35	9.8	24	7.1	0.72	
		5	0.26	1.4	3	0.9	0.09	
	5	10	0.29	2	6	1.8	0.18	60
		15	0.32	3	9	2.6	0.27	
		20	0.38	6.1	12	3.5	0.36	
		25	0.38	6.1	15	4.4	0.45	
		30	0.4	8	18	5.3	0.54	
	6	35	0.45	14.4	27	7.9	0.81	60
		40	0.45	14.4	30	8.8	0.9	
		50	0.5	23	36	10.6	1.08	
		60	0.5	23	36	10.6	1.08	
		5	0.3	1.65	3	0.9	0.09	
	7	10	0.35	2.71	6	1.8	0.18	50
		15	0.38	3.61	9	2.6	0.27	
		20	0.38	3.61	12	3.5	0.36	
		25	0.45	7.43	15	4.4	0.45	
		30	0.45	7.43	18	5.3	0.54	
	8	35	0.5	12.25	21	6.2	0.63	60
		40	0.5	12.25	24	7.1	0.72	
		45	0.5	12.25	27	7.9	0.81	
		50	0.55	19.53	30	8.8	0.9	
		60	0.55	19.53	36	10.6	1.08	
	10	5	0.32	1.5	3	0.9	0.09	60
		10	0.4	3	6	1.8	0.18	
		15	0.4	3	9	2.6	0.27	
		20	0.5	7	12	3.5	0.36	
		25	0.5	7	15	4.4	0.45	
	12	30	0.5	7	18	5.3	0.54	60
		35	0.55	11	21	6.2	0.63	
		40	0.55	11	24	7.1	0.72	
		45	0.6	17.4	27	7.9	0.81	
		50	0.6	17.4	30	8.8	0.9	
	13	60	0.65	23.4	36	10.6	1.08	57
		70	0.65	23.4	42	12.4	1.26	
		10	0.45	2.6	6	1.8	0.18	
		15	0.5	3.6	9	2.6	0.27	
		20	0.5	3.6	12	3.5	0.36	
	14	25	0.55	5.9	15	4.4	0.45	60
		30	0.65	10.4	18	5.3	0.54	
		35	0.65	10.4	21	6.2	0.63	
		40	0.7	15.4	24	7.1	0.72	
		45	0.75	21	22	7.9	0.81	
	15	50	0.75	21	27	8.8	0.9	55
		60	0.8	27.6	31	10.6	1.08	
		70	0.8	27.6	40	12.4	1.26	
		80	0.8	27.6	48	14.1	1.44	
		15	0.6	3.5	9	2.6	0.27	
	16	20	0.7	5.6	12	3.5	0.36	60
		25	0.7	5.6	15	4.4	0.45	
		30	0.8	9.6	18	5.3	0.54	
		35	0.8	9.6	21	6.2	0.63	
		40	0.8	9.6	24	7.1	0.72	
	1							

外径基准型（最大压缩量 45%~75%）

■ SCHDAC: S(工作行程) = L×Fa%

① 代号	② D	③ L	d	压紧长度	S	载荷	
						(N)	(kgf)
SCHDAC	13	15	0.7	4.7	9	2.6	0.27
		20	0.7	4.7	12	3.5	0.36
		25	0.8	8	15	4.4	0.45
		30	0.8	8	18	5.3	0.54
		35	0.8	8	21	6.2	0.63
		40	0.9	12.8	24	7.1	0.72
		45	0.9	12.8	27	7.9	0.81
		50	0.9	12.8	30	8.8	0.9
		60	1	21	36	10.6	1.08
		70	1	21	42	12.4	1.26
		80	1	21	48	14.1	1.44
		15	0.75	4.3	9	2.6	0.27
		20	0.8	5.4	12	3.5	0.36
		25	0.9	7.7	15	4.4	0.45
SCHDAD	16	30	0.9	7.7	18	5.3	0.54
		35	1	12	21	6.2	0.63
		40	1	12	24	7.1	0.72
		45	1	12	27	7.9	0.81
		50	1.1	19	30	8.8	0.9
		60	1.1	19	36	10.6	1.08
		70	1.2	26.4	42	12.4	1.26
		80	1.2	26.4	48	14.1	1.44
		20	1	6	12	5.9	0.6
		25	1.1	7.7	15	7.4	0.75
		30	1.1	7.7	18	8.8	0.9
		35	1.2	10.8	21	10.3	1.05
		40	1.2	10.8	24	11.8	1.2
SCHDAD	20	45	1.3	14.3	27	13.2	1.35
		50	1.3	14.3	30	14.7	1.5
		60	1.4	19.6	36	17.7	1.8
		70	1.4	19.6	42	20.6	2.1
		80	1.5	27	48	23.5	2.4

▲所有 SCHDAC 型的两端面均未进行磨削加工

▲压紧长度为参考值。因批量不同会有若干偏差

▲使用次数: 100 万次

■ SCHDAD: S(工作行程)=L×45%

① 代号	② D	③ L	d	压紧长度	S	载荷	
						(N)	(kgf)
SCHDAD	6	5▲	0.4	2.2	2.25	1.1	0.11
		10▲	0.5	5	4.5	2.2	0.22
		15▲	0.55	7.7	6.7	3.2	0.33
		20▲	0.55	7.7	9	4.4	0.45
		25	0.6	10.8	11.2	5.5	0.56
		30	0.65	15.6	13.5	6.6	0.67
		35	0.65	15.6	15.7	7.6	0.78
		40	0.65	15.6	18	8.8	0.9
		45	0.65	15.6	20	9.8	1
		50	0.7	23.1	22.5	10.8	1.1
		60	0.7	23.1	27	12.7	1.3
		70	0.75	30.8	31.5	14.7	1.5
		10	0.6	5.4	4.5	2.2	0.22
		15	0.65	7.2	6.7	3.2	0.33
SCHDAD	8	20	0.7	10.5	9	4.4	0.45
		25	0.7	10.5	11.2	5.5	0.56
		30	0.75	13.5	13.5	6.6	0.67
		35	0.75	13.5	15.7	7.6	0.78
		40	0.8	18.4	18	8.8	0.9
		45	0.8	18.4	22.5	10.8	1.1
		50	0.85	26.4	27	12.7	1.3
		60	0.85	26.4	31.5	14.7	1.5
		70	0.85	26.4	36	17.7	1.8
		10	0.65	4.6	4.5	2.2	0.22
		15	0.65	4.6	6.7	3.2	0.33
		20	0.8	9.6	9	4.4	0.45
		25	0.8	9.6	11.2	5.5	0.56
SCHDAD	10	30	0.85	12.8	13.5	6.6	0.67
		35	0.85	12.8	15.7	7.6	0.78
		40	0.9	17	18	8.8	0.9
		45	0.9	17	20	9.8	1
		50	0.9	17	22.5	10.8	1.1
		60	1	28	27	12.7	1.3
		70	1	28	31.5	14.7	1.5
		80	1	28	36	17.7	1.8
		15	0.8	6.8	6.7	3.2	0.33
		20	0.8	6.8	9	4.4	0.45
		25	0.8	6.8	11.2	5.5	0.56
		30	0.9	10.8	13.5	6.6	0.67
SCHDAD	12	35	1	17	15.7	7.6	0.78
		40	1	17	18	8.8	0.9
		45	1	17	20	9.8	1
		50	1.1	26.4	22.5	10.8	1.1
		60	1.1	26.4	27	12.7	1.3
		70	1.1	26.4	31.5	14.7	1.5
		80	1.2	39.6	36	17.7	1.8
		15	0.8	5.6	6.7	3.2	0.33
		20	0.8	5.6	9	4.4	0.45
		25	0.85	7.2	11.2	5.5	0.56
		30	1	14	13.5	6.6	0.67
SCHDAD	13	35	1	14	15.7	7.6	0.78
		40	1	14	18	8.8	0.9
		45	1.1	21.5	20	9.8	1
		50	1.1	21.5	22.5	10.8	1.1
		60	1.1	21.5	27	12.7	1.3
		70	1.2	30	31.5	14.7	1.5
		80	1.2	30	36	17.7	1.8
		15	0.9	5.6	6.7	3.2	0.33
		20	1	7.7	9	4.4	0.45
		25	1	7.7	11.2	5.5	0.56
		30	1.1	12.1	13.5	6.6	0.67
SCHDAD	16	35	1.1	12.1	15.7	7.6	0.78
		40	1.2	18	18	8.8	0.9
		45	1.2	18	20	9.8	1
		50	1.2	18	22.5	10.8	1.1
		60	1.3	26	27	12.7	1.3
		70	1.3	26	31.5	14.7	1.5
		80	1.4	35	36	17.7	1.8
		20	1.2	7.2	9	8.8	0.9
		25	1.3	9.1	11.3	11.1	1.13
		30	1.4	11.9	13.5	13.2	1.35
SCHDAD	20	35	1.4	11.9	15.8	15.5	1.58
		40	1.5	15.8	18	17.7	1.8
		45	1.5	15.8	20.3	19.9	2.03
		50	1.6	20.8	22.5	22.1	2.25
		60	1.6	20.8	27	26.5	2.7
		70	1.7	26.4	31.5	30.9	3.15
		80	1.7	26.4	36	35.3	3.6

▲ kgf(载荷) = N/mm × 0.101972 × S(工作行程) kgf=N×0.101972

▲所有带▲号的 SCHDAD 型两端面均未进行磨削加工

▲压紧长度为参考值。因批次不同会有少许差异

▲理论使用次数: 100 万次 (非保证值)